

*SPECIFICATION AMENDMENTS*

Replace the paragraph beginning at page 2, line 14 with:

Preferably, the pickup head has a rotary brush therein caused to rotate ~~my~~ by airflow induced by the suction fan.

Replace the paragraph beginning at page 4, line 19 with:

Within the cyclone chamber 2 there is an upper tube 1 and an air inlet tract 3 beside it. A frusto-conical flange 4 depends from the bottom of the upper tube 1 and flares outwardly therefrom. Beneath the flange at the bottom of the cyclone chamber 2 there is a funnel 60 that converges inwardly in a downward direction en route to the dust receptacle 5. There is ~~and an~~ an O-ring 9 between the cyclone chamber 2 and dust receptacle 5.